
## SURVEY PLAT


## RHODES


Surveying

WIFW.RHODESSURFEYING.COM



65





**CHACKBAY** 

LANE

THE ABOVE DESCRIBED PROPERTY DOES NOT LIE IN A FLOOD HAZARD AREA ACCORDING TO THE F.E.M.A. FLOOD INSURANCE RATE MAP COMMUNITY PANEL NO. 48113C0365J ZONE X 08/23/2001

BARRY S. RHODES Registered Professional Land Surveyor (972) 475—8940

This is to certify that I have, this date, made a careful and accurate survey on the ground of property located at No. 7007 CHACKBAY LANE , in the city of DALLAS Texas. Lot No. 65 , Block No. 26/6129

of ENCLAVE AT GROVE HILL NO. 2 , an addition to the City of DALLAS (1974)

The plat hereon is true, correct, and accurate representation of the property as determined by survey, the lines and dimensions of said property being as indicated by the plat the size, location and type of building and improvements are as shown, all improvements being within the boundaries of the property, set back from property lines the distance indicated.

THERE ARE NO ENCROACHMENTS, CONFLICTS, OR PROTRUSIONS, EXCEPT AS SHOWN.

Scale: 1" = 20'Date: 11/21/2012G. F. No.: 21200250

Job no.: 90186

Drawn by: <u>CW</u>

TEXT

IMPROVEMENTS

TERM BOUNDARY LINE

IMPROVEMENT/SETBACK

IMPRESIDENCE/FENCES

THIS SURVEY WAS PERFORMED EXCLUSIVELY FOR PRIORITY TITLE
USE OF THIS SURVEY FOR ANY OTHER PURPOSE OR OTHER PARTIES SHALL BE AT THEIR RISK AND UNDERSIGNED IS NOT RESPONSIBLE TO OTHERS FOR ANY LOSS RESULTING THEREFROM.

