BAKER STREET HOME INSPECTION SERVICES INC.



3230 Yonge Street, Suite 1717 Toronto, Ontario M4N 3P6 Telephone: 416-483-3535

Website: www.bakerstreet-hi.ca Email: info@bakerstreet-hi.ca

Attention: Prospective Purchasers

This report has been prepared for the seller to provide them with a better understanding of the condition of their house. The seller has accepted this report as an accurate assessment of the functional condition of their property at the time of the inspection. The report represents our observed opinions.

Baker Street Home Inspection Services Inc. will remain available over the phone to any interested party to answer questions regarding this property. The reader is cautioned that the report will not convey all information that a prospective buyer may deem relevant. As such, all interested buyers are advised to have their own inspection.

Should any party require further information, Baker Street Home Inspection Services Inc. will provide a 1 ½ hour on-site orientation of the house for a fee of \$325 + HST, based on a typical 3-bedroom house. This general review inspection is essential to understand the written report and to compare your expectations, intended use and any special needs with the current condition of the subject property. Interested parties should be advised that without this general review, our obligations and liability can only remain with the seller.

Please note that Baker Street Home Inspection Services Inc. remains available to all their clients, indefinitely, to address any questions or concerns.

Should you wish clarification, please do not hesitate to contact our office.

Sincerely,

BAKER STREET HOME INSPECTION SERVICES INC.



BAKER STREET HOME INSPECTION SERVICES INC.

3230 Yonge Street, Suite 1717

Toronto, Ontario M4N 3P6

Telephone: 416-483-3535 Email: info@bakerstreet-hi.ca

Website: www.bakerstreet-hi.ca

PRELIMINARY BUILDING INSPECTION REPORT



Property Address:

86 Cortleigh Blvd.

Date of inspection:

September 8, 2025

Prepared By:

Ian Smith, RHI

BAKER STREET HOME INSPECTION SERVICES INC.

3230 Yonge St, Suite 1717 Toronto, Ontario M4N 3P6

P: 416-483-3535 E: info@bakerstreet-hi.ca

W: www.bakerstreet-hi.ca

Over 50,000 Inspections Performed Since 1985

Residential Property Inspections Commercial Property Inspections Income Property Inspections Inspections of Newly Constructed Homes Pre-Delivery Inspections



BAKER STREET HOME INSPECTION SERVICES INC.

3230 Yonge Street, Suite 1717

Toronto, Ontario M4N 3P6

Telephone: 416-483-3535 Email: info@bakerstreet-hi.ca

Website: www.bakerstreet-hi.ca

PRELIMINARY BUI	LDING INSPECTION REPO	ORT								
Property Inspected 86 Cortleigh Blvd.				Municipality Toronto				to		
Inspection Date Septer	mber 8, 2025	Time 9am	to	12pm	I	nspector	Ian Smith, RI	łI	-	
Name of Client C/O R	tobert Greenberg									
General Information										
GENERAL DESCRIE	PTION OF THE BUILDING									
Type of Structure			(Occupancy T	Гуре					
1 Storey	Detached		[Single fan	nily dwellin	g	Duplex			
✓ 2 Storey	Semi-detached	l	[Basement	apt. added		Triplex			
3 Storey	Row house/Fu	ılly attached	[Multi-pur	pose occupa	ancy	Fourplex			
Back split	Condominium	/Townhouse	[Multiplex			
Side split	Highrise condo	ominium								
			[
Approximate age of bui	ilding is 55+/- y	ears. Building has	been substan	tially renova	ted		years ago.			
Construction type: soli										
A new structure has bee	en built approximately	years a	ago on		year ol	d founda	tions.			
GENERAL CONDIT	IONS AND PERSPECTIVES	AT THE TIME C	OF THE PRI	ELIMINAR	 Y INSPEC	TION				
This building is in above	ve average	ional condition in co	omparison to	other similar	r age and siz	ze homes	in the neighbor	urhood.		
	an average amount of repair cor	nsideration 🔻 i	n comparisor	n to other sin	nilar age hoi	mes/build	lings in the neig	ghborhood.		
	of similar age/size and quality v)- \$6500 ▼	for annual g	eneral repai	rs and on	-going mainter	ance.		
You will require \$ 11,0	00.00+ (minimum) to a	address the function	al concerns l	isted in the tl	he report ov	er the ne	xt 0-2 ▼	years.		
MAJOR SYSTEMS -	GENERAL DESCRIPTION	AND CONDITION	NS:							
Roofing systems: asp	halt shingles Secondar	y roofing system:	flat roof men	nbrane 🔻		-				
Exterior wall systems:	solid masonry	▼ Secondary wall	siding: woo	od siding				_		
Windows(general):	Mostly original: wood sashes	~								
Electrical Systems: M	Main service size 200 ▼ amp	circuit breakers		▼ Predomir	nant branch	wiring:	romex/copper			-
Heating System: Fuel	l type: natural gas 🔻 Age of	central heating appl	iance: 12+		years S	ystem typ	e: high-efficie	ency forced air f	urnace	-
Cooling System: Syst	em type: central A/C-low velo	city	Age of cool	ing equipme	nt: 12+		years App	orox. tons: 4.0 t	ons 🔻	
Plumbing System: M	ain supply: 1 inch copper line			▼ Predo	ominant wat	er lines	copper	▼	~	
General Interiors: go	ood overall functional condition		-							
REQUIRED REPAIR	RS/MAJOR SYSTEMS AND	COMPONENTS A	PPROACH	ING END (OF EXPEC	TED LI	FE SPAN			
Miscellaneous exterior	repairs & future maintenance		▼ /	Time frame	0-2	years B	udget \$ 6,000.	00+		
Miscellaneous interior	repairs & future maintenance		T	Time frame	0-2	years B	udget \$ 5,000.	00+		
			₩.	Time frame	-	years B	udget \$			
			-	Time frame	₹	years B	udget \$			
			▼ ′	Time frame		years B			Calcu	ılate
				Time frame		years B				
				Time frame		years B	_			
HOMEOWNED INCI	URANCE CONCERNS		<u> </u>	i iiie irame		years B	udget \$			
	MAINCE CUNCERNS							<u></u>		
✓ None Identified		V			_					
		~			~					

YOUR RECOMMENDED COURSE OF IMMEDIATE ACTION AND CONSIDERATION:

Please review the preliminary report in its entirety and ask for clarification on any matter. This page must not be relied upon in isolation. Prior to continuing with the next step of the transaction/project consider the issues listed in the report. We advise you to consult with your realtor or lawyer regarding options on how to proceed. Also instruct your lawyer to obtain Title Insurance for you. You should request additional inspections as outlined in the full report to address your special concerns and/or matters that we can not inspect. You must also factor the limitations of the building inspection in your decision making process. 80% of first year repairs should be revealed: NOT 100%. Therefore you must anticipate and budget for the 20% first year repairs that will not be discovered by a visual inspection. You must ask the seller for invoices/applicable warranties/plans and/or permits for work completed in the last five years.

✓ CONSIDER ALL DEFICIENCIES RELATED TO HEALTH/SAFETY ISSUES AND UNCONTROLLED WATER PROBLEMS AS URGENT MAT

✓ OBTAIN CONTRACTORS QUOTE/REPAIR SPECIFICATIONS ON ANY MAJOR REPAIRS NOTED HEREIN IMMEDIATE

OTHER RECOMMENDATIONS

A camera inspection of the main building drain is recommended.		-	
CO emission test of furnace recommended		-	
An Arborist is recommended for trimming/maintenance of trees on	property	-	
		-	
		▼	
ADDITIONAL INFORMATION REQUIRED			
		▼	
		-	
		-	
		-	
FURTHER CLARIFICATION REGARDING:			
	is required of the:		▼
-	is required of the:		₩

IMPORTANT NOTE ABOUT THE SUMMARY This summary report should not be considered as a complete home and property inspection. Please review the entire report prior to proceeding with the next step of the transaction. Please be cautioned that the following noted items represent the minimum amount of work that you will need to address in the foreseeable future. The inspection process is a two-part system: the verbal survey and the full written report. This report is not transferable to third parties as it will not clearly convey the information contained herein.

UNDERSTANDING THE SERVICES INCLUDED IN A HOME INSPECTION AND LIMITATIONS OF THE SERVICE:

- 1) The preliminary inspection report issued by the inspector is prepared with reasonable skill and care. This consulting service is limited to the physical evidence that was visually accessible at the time of the inspection. This report is not transferable to anyone other than the client as this report does not include the verbal information imparted by the inspector which is vital to fully understand the service and contract.
- 2) The required repairs to the building include, but are not limited to, what is reported herein due to the limitations and restrictive nature of the visual inspection. The client is hereby warned that not all deficiencies will be discovered. At best 80% of the first year repairs should be revealed; not 100%. Determining the presence of mold, fungi, asbestos and other indoor air quality contaminants are specifically not included.
- 3) The preliminary inspection is partially designed to reduce your risk of buying an older home. However we cannot eliminate this risk.

 The inspector/inspection firm will not assume any of your risk in buying an older property. Further inspections by specialists are required. (See Appendix.)
- 4) The client is advised to annually budget at least 1% of the building's value for general maintenance and unforeseen repairs.
- 5) The client is warned that resultant damages may occur to the building systems or components if the recommended repairs in this report are not carried out in a timely manner. This is especially the case in matters concerning electrical and occupant safety as well as uncontrolled water/vapour.
- 6) Cost estimates if provided in this report are minimums and are intended to be a rough guideline only. Estimates are based on the most cost effective solution to address the problem and will not include betterment. Obtain accurate cost estimates from contractors immediately.
- 7) The preliminary inspection does not cover code compliance issues, statuatory regulations or information to obtain building/homeowners insurance.
- 8) The preliminary inspection process is conducted in a fair and impartial manner. Accordingly this report is not provided as an aid for negotiation in a real estate transaction. We do not overstate or under value any issue to benefit any party.
- 9) The purchaser is advised to ask the property owner if they are aware of any defects that would not normally be detected by a visual inspection.
 The purchaser is advised to revisit the property, before closing, to verify that functional conditions remain unchanged or retain the inspector for this task.
- 10) The client/buyer hereby acknowledges they are contractually obliged to contact the inspector immediately to arrange a site visit at no extra expense in the event of an unforeseen and/or unreported problem or upon receiving a conflicting opinion and also prior to undertaking any corrective work.