

### Continuous Radon Monitor

Model Number: 1028  
Calibration Date: 10/29/2018  
Monitor Time: 6/14/2019 19:48

Serial Number: 71436010  
CF: 2.68

### Inspection Company

ProSpect Property Inspections  
ProSpect Property Inspections  
62 Exeter Road  
Newmarket, NH-03857  
Phone Number: 603-200-0070  
License Number: PMS 50132

### Billing Information

3 Langelley Drive  
Lee, NH-03861

### Site Information


3 Langelley Drive  
Lee, NH-03861

### Test Summary

Start Time: 06/12/2019 18:56  
End Time: 06/14/2019 17:56  
Measurement Interval(hr): 1.0  
Exposure Time: 1 Days 23 hrs

Overall Avg: 0.5 pCi/l  
EPA Avg: 0.5 pCi/l

### Continuous Radon Monitor Model 1028 S/N: 71436010



Overall Avg: 0.5

No Motion Detected

◆ Radon pCi/l    ● Motion Errors    — Action Level

\*\*\*\*\* 06/12/2019 \*\*\*\*\*

| Time  | Counts<br>pCi/l | Flags |
|-------|-----------------|-------|
| 19:56 | 0.0             |       |
| 20:56 | 0.0             |       |
| 21:56 | 1.1             |       |
| 22:56 | 0.4             |       |
| 23:56 | 0.4             |       |

\*\*\*\*\* 06/13/2019 \*\*\*\*\*

| Time  | Counts<br>pCi/l | Flags |
|-------|-----------------|-------|
| 00:56 | 0.4             |       |
| 01:56 | 1.5             |       |
| 02:56 | 0.7             |       |
| 03:56 | 0.7             |       |
| 04:56 | 0.4             |       |
| 05:56 | 1.1             |       |
| 06:56 | 1.1             |       |
| 07:56 | 0.4             |       |
| 08:56 | 1.1             |       |
| 09:56 | 0.7             |       |
| 10:56 | 0.0             |       |
| 11:56 | 0.4             |       |
| 12:56 | 0.7             |       |
| 13:56 | 0.7             |       |
| 14:56 | 0.4             |       |
| 15:56 | 0.0             |       |
| 16:56 | 1.1             |       |
| 17:56 | 0.4             |       |
| 18:56 | 0.4             |       |
| 19:56 | 0.4             |       |
| 20:56 | 0.0             |       |
| 21:56 | 0.0             |       |
| 22:56 | 0.4             |       |
| 23:56 | 0.7             |       |

\*\*\*\*\* 06/14/2019 \*\*\*\*\*

| Time  | Counts<br>pCi/l | Flags |
|-------|-----------------|-------|
| 00:56 | 0.4             |       |
| 01:56 | 0.7             |       |
| 02:56 | 1.5             |       |
| 03:56 | 0.4             |       |
| 04:56 | 0.4             |       |
| 05:56 | 0.7             |       |
| 06:56 | 0.4             |       |
| 07:56 | 0.4             |       |
| 08:56 | 0.4             |       |

\*\*\*\*\* 06/14/2019 \*\*\*\*\*

| Time  | Counts<br>pCi/l | Flags |
|-------|-----------------|-------|
| 09:56 | 0.7             |       |
| 10:56 | 0.4             |       |
| 11:56 | 0.7             |       |
| 12:56 | 0.4             |       |
| 13:56 | 0.7             |       |
| 14:56 | 0.0             |       |
| 15:56 | 0.4             |       |
| 16:56 | 0.4             |       |
| 17:56 | 0.0             |       |

Error Flags:

M Motion:

Inspector Signature \_\_\_\_\_

PC Software Version: 2.2.0

Embedded Software Version: 109

## Radon Risk Information

---

Radon is the second leading cause of lung cancer, after smoking. The US EPA and Surgeon General strongly recommend taking further action when a homes radon test results are 4.0 pCi/l or greater. The concentration of radon in the home is measured in picocuries per liter of air (pCi/l). Radon levels less than 4.0 pCi/l still pose some risk and in many cases may be reduced. If the radon level in the home is between 2.0 and 4.0 pCi/l, the EPA still recommends that you consider fixing the home. The average indoor radon level is estimated to be about 1.3 pCi/l; roughly 0.4 pCi/l of radon is normally found in the outside air. The higher the home radon level, the greater the health risk. Even homes with very high radon levels can be reduced to below 4.0 pCi/l and many homes can be reduced to 2.0 pCi/l or less.

---

## Understanding Time-Sensitive Testing Protocols

---

### *Continuous Monitor Results:*

Single test result average 4.0 pCi/l or more

Fix the home

Single test result average between 2.0 and 4.0 pCi/l

Consider fixing the home

Less than 4.0 pCi/l: confirm the low result by testing again at least every two years and whenever significant changes to the home structure or mechanical systems occur.

Test during different seasons and different weather conditions to reduce your risk of exposure.

---