

Service Slip/Invoice

HAMPTON ROADS TERMITE &
PEST CTRL
609 INNOVATION DRIVE
CHESAPEAKE, VA 23320
757-436-3333

INVOICE: 581554
DATE: 06/29/2026
ORDER: 581554

Bill To: [109800]
RW TOWNE TITLE
1101 LASKIN ROAD
VIRGINIA BEACH, VA 23451

Work Location: [184867]
5413 STUDELEY AVENUE
NORFOLK, VA 23508

Work Date	Time	Target Pest	Technician	Time In
06/23/2026			TF	
			TIMOTHY WYNN	
Purchase Order	Terms	Last Service	Map Code	Time Out
	NET 30 DAYS	06/23/2026		
			Lic:73334-C	

Service	Description	Price
LTR	TERMITE AND MOISTURE REPORTS	\$0.00
CR	SISTER TWENTY 2X10X8	\$3,500.00
CR	CUT OFF AND REPLACE 24FT OF TRIPLE 2X8	\$3,750.00
CR	REPAIR FIVE 2X10 BAND BOARD	\$450.00
CR	REPAIR 16FT OF DOUBLE 2X10	\$1,900.00
TERM	TERMITE TREATMENT	\$850.00
RE	POWDER POST BEETLE TREATMENT AND STRAIGHTEN MOISTURE BARRIER	\$395.00
SUBTOTAL		\$10,845.00
TAX		\$0.00
AMT. PAID		(\$10,845.00)
TOTAL		\$0.00
AMOUNT DUE		\$0.00

WE ACCEPT CASH, CHECKS AND CREDIT CARDS

CREDIT CARD PAYMENTS CAN BE MADE VIA OUR WEBSITE

WWW.HAMPTONROADSTERMITE.COM

THANK YOU FOR YOUR BUSINESS!

* Balances outstanding over 30 days from the date of service may be subject to a late fee of the lesser of 1.5% per month (18% per year) or the maximum allowed by law.
Customer agrees to pay accrued expenses in the event of collection.

I hereby acknowledge the satisfactory completion of all services rendered, and agree to pay the cost of services as specified above.

PLEASE PAY FROM THIS INVOICE

**WOOD DESTROYING ORGANISM ATTACHMENT
TO THE WOOD DESTROYING INSECT INFESTATION REPORT (FORM NPMA-33)**

This is not a structural damage report. This form may be altered. Form NPMA-33 must accompany this report and this report must be listed in Section V of the Form NPMA-33.

SECTION I. GENERAL INFORMATION

Property Address: 5413 STUDELEY AVENUE, NORFOLK, VA 23508

Inspection Company: HAMPTON ROADS TERMITE & PEST CTRL

Company Address & Phone: 609 INNOVATION DRIVE, CHESAPEAKE, VA

Inspector Name: TIMOTHY WYNN

23320, 757-436-3333

SECTION II. INSPECTION FINDINGS

This report is indicative of the condition of the subject structure(s) on the date of the inspection only and is NOT to be construed as an express or implied warranty or guarantee against latent, concealed, or future defects. Any such warranty or service agreement to provide future treatment or inspections may be provided as a separate attachment and only if indicated in Section V of Form NPMA-33. Information on the back of Form NPMA-33, *Important Consumer Information Regarding the Scope and Limitations to the Inspection* is incorporated by reference.

Based on a careful visual inspection of the readily accessible areas of the crawlspace or basement of the structure(s) inspected:

☐ A. NO VISIBLE EVIDENCE OF WOOD DECAY FUNGI WAS OBSERVED

☒ B. VISIBLE EVIDENCE OF WOOD DECAY FUNGI WAS OBSERVED AS FOLLOWS:

☒ Fungi observed (description and location): FUNGUS IN CRAWL - TREATMENT COMPLETED BY THIS COMPANY ON JULY 24, 2026

☒ Damage from wood decay fungi was noted in the following area(s): WOOD ROT TO JOISTS, BEAM AND BAND BOARD - REPAIRS COMPLETED BY THIS COMPANY ON JULY 31, 2026

☐ CORRECTIVE ACTION RECOMMENDED AS FOLLOWS: _____

Regarding visible evidence of wood decay fungi: The inspector may find wood which has been damaged by fungi. Any damage noted should be considered only as evidence of current or previous activity of wood decay fungi. If box B is checked above, IT SHOULD BE UNDERSTOOD THAT SOME DEGREE OF DAMAGE, INCLUDING HIDDEN DAMAGE, MAY BE PRESENT. The inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair. UPON RECEIPT OF THIS REPORT, THE SELLER OR THE SELLER'S AGENT SHALL NOTIFY THE BUYER THAT ANY DAMAGE SHOULD BE EXAMINED BY A QUALIFIED INDIVIDUAL TO DETERMINE ANY NEED FOR REPAIR.

☐ There is evidence of the presence of excessive moisture conditions in wood as follows: _____

SIGNATURE OF INSPECTOR

Neither I nor the company for which I am acting have had, presently have, or contemplate having any interest in the property. I do further state that neither I nor the company for which I am acting is associated in any way with any party to this transaction.

Timothy E Wynn
Signature of Inspector

73334-C
Certification or Registration No. (if applicable)

06/23/2026
Date of Inspection

STATEMENT OF BUYER AND SELLER-THIS REPORT MUST BE SIGNED BY THE BUYER AND SELLER AS APPLICABLE

This report is integral to, and a necessary part of the inspecting company's full disclosure as to the scope and inherent limitations of the inspection and report of findings. It is most important that the interested parties acknowledge this advice. The seller hereto agrees that all known property history information regarding wood decay fungi, damage from fungi, and treatment history has been disclosed to the buyer. A legible copy of this page must be returned to the inspecting company by the person ordering this inspection.

SIGNATURE OF SELLER(S) ☐ or OWNER ☐ (if refinancing)

DATE

The undersigned hereby acknowledges receipt of a copy of this report

SIGNATURE OF BUYER(S)

DATE

2019 National Pest Management Association (NPMA). This form has been developed by NPMA as a service to inspection firms. By so doing, NPMA does not certify that the inspection firm is a member in good standing of NPMA or that it is qualified to perform the inspection. NPMA is not guaranteeing the inspection firm's work. NPMA shall not be a party to any claim or action by the buyer or seller against the inspection firm solely by reason of making this report form available for use.



MOLD & MILDEW DISCLAIMER

This report is not a comprehensive moisture report regarding the entire structure and applies only to wood decay fungi (white rot, brown rot, and dry rot) and moisture conditions conducive to the growth of wood decay fungi limited to the area below the first main floor. This property was not inspected for the presence or absence of health-related molds or fungi. The inspector performing this inspection is not qualified, authorized nor licensed to inspect for health-related molds and/or fungi. Should information regarding the presence or absence of health-related molds or fungi be desired, an industrial Hygienist or health related mold professional should be contacted. Therefore, this report should not be relied upon in lieu of a complete physical inspection of the entire premises by interested parties or persons.

Seller Signature _____ Date _____

Buyer Signature _____ Date _____

Note: Both parties must sign at the time of closing.

Wood Destroying Insect Inspection Report

Notice: Please read important consumer information on **page 2**.

Section I. General Information

Inspection Company, Address & Phone

HAMPTON ROADS TERMITE & PEST CTRL
609 INNOVATION DRIVE
CHESAPEAKE, VA 23320
757-436-3333

Company's Pest Control Business Lic. No.

91000240

Date of Inspection

06/23/2026

Address of Property Inspected

5413 STUDELEY AVENUE
NORFOLK, VA 23508

Inspector's Name, Signature & Certification, Registration, or Lic. #

TIMOTHY WYNN



#73334-C

Structure(s) Inspected

SINGLE FAMILY CRAWL

Section II. Inspection Findings

This report is indicative of the condition of the above identified structure(s) on the date of inspection and is not to be construed as a guarantee or warranty against latent, concealed, or future infestations or wood destroying insect damage. **Based on a careful visual inspection of the readily accessible areas of the structure(s) inspected:**

☐ **A. No visible** evidence of wood destroying insects was observed.

☒ **B. Visible** evidence of wood destroying insects was observed as follows:

☐ 1. Live insects (description and location): _____

☒ 2. Dead insects, insect parts, frass, shelter tubes, exit holes, or staining (description and location): POWDER POST BEETLE EXIT HOLES THROUGHOUT AND SHELTER TUBES IN CRAWL

☐ 3. **Visible** damage from wood destroying insects was noted as follows (description and location): _____

NOTE: This is not a structural damage report. If box B above is checked, it should be understood that some degree of damage, including hidden damage, may be present. If any questions arise regarding damage indicated by this report, it is recommended that the buyer or any interested parties contact a qualified structural professional to determine the extent of damage and the need for repairs.

Section III. Recommendations

☐ No action and/or treatment recommended: (Explain if Box B in Section II is checked) _____

☒ Recommend action(s) and/or treatment(s) for the control of: TERMITE & POWDER POST BEETLES - TREATMENTS COMPLETED BY THIS COMPANY ON JULY 24, 2026

Section IV. Obstructions and Inaccessible Areas

The following areas of the structure(s) inspected were obstructed or inaccessible:

☐ Basement

☒ Crawlspace 5 13 24

☒ Main Level 1 3 4 6 7 8 9 13

☒ Attic 11 21

☒ Garage 1 3 4 6 7 8 9 13

☒ Exterior 13 16 17

☐ Porch

☐ Addition

☐ Other

The inspector may write out obstructions or use the following optional key:

- | | |
|-------------------------|--|
| 1. Fixed ceiling | 15. Standing water |
| 2. Suspended ceiling | 16. Dense vegetation |
| 3. Fixed wall covering | 17. Exterior siding |
| 4. Floor covering | 18. Window well covers |
| 5. Insulation | 19. Wood pile |
| 6. Cabinets or shelving | 20. Snow |
| 7. Stored items | 21. Unsafe conditions |
| 8. Furnishings | 22. Rigid foam board |
| 9. Appliances | 23. Synthetic stucco |
| 10. No access or entry | 24. Duct work, wiring, and/or plumbing |
| 11. Limited access | 25. Spray foam insulation |
| 12. No access beneath | 26. Equipment |
| 13. Only visual access | |
| 14. Cluttered condition | |

Section V. Additional Comments and Attachments

(these are an integral part of the report) **ALL REPAIRS RENDERED BY THIS COMPANY ARE STRUCTURALLY SOUND, TO CODE, WORKMANSHIP AND MATERIALS WARRANTIED FOR ONE FULL YEAR.**

CONTRACTORS LICENSE #2705 017073, EXPIRES 12-31-26

Attachments MOISTURE REPORT AND MOLD DISCLAIMER

Signature of Seller(s) or Owner(s) if refinancing. Seller discloses to the buyer all information, to their knowledge, regarding W.D.I. infestation, damage, repair, and treatment history.

X

Signature of Buyer. The undersigned hereby acknowledges receipt of a copy of both page 1 and page 2 of this report and understands the information reported.

X

Important Consumer Information Regarding the Scope and Limitations of the Inspection

Please read this entire page as it is part of this report. Please refer to the NPMA Suggested Guidelines for instructions on completing this report. This report is not a guarantee or warranty as to the absence of wood destroying insects nor is it a structural integrity report. The inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair.

- 1. About the Inspection:** A visual inspection was conducted in the readily accessible areas of the structure(s) indicated (see Page 1) including attics and crawlspaces which permitted entry during the inspection. The inspection included probing and/or sounding of unobstructed and accessible areas to determine the presence or absence of visual evidence of wood destroying insects. The WDI inspection firm is not responsible to repair any damage or treat any infestation at the structure(s) inspected, except as may be provided by separate contract. Also, wood destroying insect infestation and/or damage may exist in concealed or inaccessible areas. The inspection firm cannot guarantee that any wood destroying insect infestation and/or damage disclosed by this inspection represents all of the wood destroying insect infestation and/or damage which may exist as of the date of the inspection. **For purposes of this inspection, wood destroying insects include: termites, carpenter ants, carpenter bees, and reinfesting wood boring beetles. This inspection does not include mold, mildew or noninsect wood destroying organisms.** This report shall be considered invalid for purposes of securing a mortgage and/or settlement of property transfer if not used within ninety (90) days from the date of inspection. **This shall not be construed as a 90-day warranty.** There is no warranty, express or implied, related to this report unless disclosed as required by state regulations or a written warranty or service agreement is attached.
- 2. Treatment Recommendation Guidelines Regarding Subterranean Termites:** Treatment or corrective action should be recommended if live termites are found. If no evidence of a previous treatment is documented and evidence of infestation is found, even if no live termites are observed, treatment or corrective action by a licensed pest control company should be recommended. Treatment or corrective action may be recommended if evidence of infestation is observed, and a documented treatment occurred previously, unless the structure is under warranty or covered by a service agreement with a licensed pest control company.
For other Wood Destroying Insects, please refer to the NPMA suggested guidelines for added guidance on actions and or treatment.
- 3. Obstructions and Inaccessible Areas:** No inspection was made in areas which required the breaking apart or into, dismantling, removal of any object, including but not limited to: moldings, floor coverings, wall coverings, siding, fixed ceilings, insulation, furniture, appliances, and/or personal possessions; nor were areas inspected which were obstructed or inaccessible for physical access on the date of inspection. Your inspector may write out inaccessible areas or use the key in Section IV. Crawl spaces, attics, and/or other areas may be deemed inaccessible if the opening to the area is not large enough to provide physical access for the inspector or if a ladder was required for access. Crawl spaces (or portions thereof) may also be deemed inaccessible if there is less than 24 inches of clearance from the bottom of the floor joists to the surface below. If any area which has been reported as inaccessible is made accessible, the inspection company may be contacted for another inspection. An additional fee may apply.
- 4. Consumer Maintenance Advisory Regarding Integrated Pest Management for Prevention of Wood Destroying Insects.** Any structure can be attacked by wood destroying insects. Homeowners should be aware of and try to eliminate conditions which promote insect infestation in and around their structure(s). Factors which may lead to wood destroying insect infestation include: earth to wood contact, foam insulation at foundation in contact with soil, faulty grade, improper drainage, firewood against structure(s), insufficient ventilation, moisture, wood debris in crawlspace, wood mulch or ground cover in contact with the structure, tree branches touching structure(s), landscape timbers and wood decay. Should these or other conditions exist, corrective measures should be taken in order to reduce the chances of infestation of wood destroying insects and the need for treatment.
- 5. Neither the inspecting company nor the inspector has had, presently has, or contemplates having any interest in the property inspected.**