



**DAVIS**  
**Septic Tank Service**  
831 Double Springs Road  
Monroe, GA 30656  
(770) 267-9765

Date 10-3-25  
Kathy House  
159 Cole Cir.  
Bethlehem 770 906-5639

**PRICE**

**ARTICLE AND DESCRIPTION**

1. SERVICED SEPTIC TANK LAST: Date or Yrs. Ago \_\_\_\_\_ By \_\_\_\_\_

2. Depth 2' ☒ ft. ☐ in.

<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

☐ 750  
☒ 1000  
☐ 1500

Distribution Box ☐ Yes ☐ No  
Other \_\_\_\_\_

**3. LINES FROM TANK BACK INTO HOME:**

Material: ☐ Concrete to Cast Iron  
☐ Concrete to Plastic  
☐ Clay to Cast Iron  
☐ Clay to Plastic  
☐ Orange Burg to Cast Iron  
☐ Orange Burg to Plastic

☐ Cast Iron  
☒ Plastic Sch 40  
☐ Plastic Sch 20  
☐ Plastic Corrugated  
☐ Other Specify \_\_\_\_\_

☒ Line OK, as is at this time  
☐ Line OK at this time, but should be replaced to avoid problems in the future.  
☐ Line gone, must be replaced now.  
☐ Roots growing in line, cut out but will grow back. Line should be replaced.

☐ Use 4" Sch 40 plastic with 2 way cleanout and plug.  
☐ How many ft. from home \_\_\_\_\_  
☐ Depth of line if known \_\_\_\_\_

**4. OPERATION OF LINE:**

☒ Clear at this time  
☐ Clogged; which was caused by...  
☐ Roots  
☐ Grease  
☐ Damaged line  
☐ Line dropped behind tank wall

Line Clogged was: ☐ Main line  
☐ Kitchen line  
☐ Vent

☐ Washing Machine line  
☐ Bathroom

Line unclogged by means of: ☐ Water Pressure NO CHARGE  
☐ Machine NO CHARGE  
☐ Other \_\_\_\_\_

If Damaged: ☐ No. of ft. from tank \_\_\_\_\_  
☐ Estimate of repair \_\_\_\_\_

**5. SANITARY T'S IN TANK:**

Entering: ☒ Clear at this time  
☐ Partially clogged  
☐ Clogged Completely  
☐ Amount of grease in gals. \_\_\_\_\_  
☐ Clogged, due to line from home inside tank to far.


Leaving: ☒ OK  
☐ OK, but showing signs of decay  
☐ Rebuilt with concrete  
☐ Replaced with Sch 40 plastic

Line between tank and field system:  
☐ Concrete  
☐ Plastic Sch 20  
☒ Plastic Sch 40  
☒ OK at this time  
☐ Needs replacing in future  
☐ We replaced with tee as far as possible without Digging

6. CONDITION OF TANK: Fluid ☒ Normal  
Level ☐ Too Full

Scum Level 4"  
Sludge Level 6"

Tank waste: ☒ Perfect ☐ 1/3 Solid ☐ 1/2 Solid  
☐ 2/3 Solid ☐ 3/4 Solid ☐ Solid



**7. CONDITION OF FIELD SYSTEM:**

☐ Working properly per tank markings and visual surface  
☒ Has been saturated  
☐ Complete system saturated  
☐ Water ☐ Waste ☐ Both  
☐ Blocked at:  
☐ Stepdown \_\_\_\_\_  
☐ Ft. from tank \_\_\_\_\_

☐ Concrete tiles  
☐ Clay tiles  
☒ 4" corrugated  
☐ Chambers  
☐ Other \_\_\_\_\_

☐ Will have to replace at some point in the future  
☐ Gone, must replace due to age of system and lack of proper maintenance  
☐ System dislocated from tank, due to solid pipe leaving tank; crushed, dissolved, or collapsed  
☒ Back flushed and pumped from tank  
☒ Working as should at this time  
☐ Flowed back

8. WATER LEAKS IN HOME ☒ None at this time ☐ Drip ☐ Trickle ☐ Stream ☐ Any leak no matter how small will cause system to fail  
**MUST BE CORRECTED:**

☐ Most of the time water leaks are from one or more commodes, and most of the time homeowner cannot hear this leak.

☐ Water level in the storage tanks may be too high.  
☐ Rubber flap valve needs to be checked with food coloring.

☐ Homeowners said they would check for leaks.

9. PLEASE DO NOT PUT INTO SYSTEM: ☐ Grease - Dispose of in household trash; also wipe pans and plates free of excess grease before rinsing or washing  
☐ Tampon Applicators ☐ Sanitary Napkins ☐ Baby Wipes ☐ Facial Tissue ☐ Q-Tips ☐ Razor Blades

Line unclogged by means of: ☐ Water Pressure NO CHARGE  
☐ Machine NO CHARGE  
☐ Other \_\_\_\_\_

If Damaged: ☐ No. of ft. from tank \_\_\_\_\_  
☐ Estimate of repair \_\_\_\_\_

### 5. SANITARY T'S IN TANK:

Entering: ☒ Clear at this time  
☐ Partially clogged  
☐ Clogged Completely  
☐ Amount of grease in gals. \_\_\_\_\_  
☐ Clogged, due to line from home inside tank to far.

Leaving: ☒ OK

☐ OK, but showing signs of decay  
☐ Rebuilt with concrete  
☐ Replaced with Sch 40 plastic

Line between tank and field system:

☐ Concrete  
☐ Plastic Sch 20  
☒ Plastic Sch 40  
☒ OK at this time  
☐ Needs replacing in future  
☐ We replaced with tee as far as possible without Digging

6. CONDITION OF TANK: Fluid Level ☒ Normal ☐ Too Full

Scum Level 4"  
Sludge Level 6"

Tank waste: ☒ Perfect ☐ 1/3 Solid ☐ 1/2 Solid  
☐ 2/3 Solid ☐ 3/4 Solid ☐ Solid



### 7. CONDITION OF FIELD SYSTEM:

☐ Working properly per tank markings and visual surface  
☒ Has been saturated  
☐ Complete system saturated  
☐ Water ☐ Waste ☐ Both  
☐ Blocked at:  
☐ Stepdown \_\_\_\_\_  
☐ Ft. from tank \_\_\_\_\_

☐ Concrete tiles  
☐ Clay tiles  
☒ 4" corrugated  
☐ Chambers  
☐ Other \_\_\_\_\_

☐ Will have to replace at some point in the future  
☐ Gone, must replace due to age of system and lack of proper maintenance  
☐ System dislocated from tank, due to solid pipe leaving tank; crushed, dissolved, or collapsed  
☒ Back flushed and pumped from tank  
☒ Working as should at this time  
☐ Flowed back

### 8. WATER LEAKS IN HOME MUST BE CORRECTED:

☒ None at this time ☐ Drip ☐ Trickle ☐ Stream ☐ Any leak no matter how small will cause system to fail

☐ Most of the time water leaks are from one or more commodes, and most of the time homeowner cannot hear this leak.

☐ Water level in the storage tanks may be too high.  
☐ Rubber flap valve needs to be checked with food coloring.

☐ Homeowners said they would check for leaks.

9. PLEASE DO NOT PUT INTO SYSTEM: ☐ Grease - Dispose of in household trash; also wipe pans and plates free of excess grease before rinsing or washing  
☐ Condoms ☐ Cigarette Butts ☐ Tampons ☐ Tampon Applicators ☐ Sanitary Napkins ☐ Baby Wipes ☐ Facial Pads ☐ Q-Tips ☐ Razor Blades  
☐ Food from garbage disposal ☐ Small plastic packaging from anything on or not on this list ☐ Remember, only human waste and bathroom tissue should go into system. No matter what is advertised.

10. TREES OR BUSHES: ☐ Must go ☐ Should go Type \_\_\_\_\_ Location \_\_\_\_\_

11. SPACE WASHING MACHINE DAYS: ☐ A system must have time to recover from daily use, so it is wise and most important that wash days are spaced out about 2-3 days per week. Not all on the same day.

12. BLEEDOUT POINT AT: ☐ Tank ☒ Stepdown ☐ Weakest place in system ☐ Backup in home Approx. distance from tank \_\_\_\_\_

13. LOCATION SERVICED FROM: ☒ Driveway ☐ Turn around ☐ Street ☐ Other \_\_\_\_\_ No. of hoses used 3

++14. TANK PUMPING DOES NOT SOLVE PROBLEMS ONLY PREVENTS IF PROPERLY CARED FOR, CAN LAST A LIFETIME. IF NOT, IT WILL RESULT IN COSTLY REPLACEMENT OR REPAIR IN APPROXIMATELY 20 YEARS, PLUS OR MINUS.

REMARKS-OTHER

to service (pump) tank

Letter of inspection

Thank  
you

Water getting thru whole system

~~Building is over~~ Building is partially over drain lines But does not appear to be causing a problem

TERMS NET UPON RECEIPT/CK. No. Paid

780.00  
100.00  
880.00 total