

YAMH 52523

STATE OF OREGON
WATER SUPPLY WELL REPORT
 (as required by ORS 537.765)

Instructions for completing this report are on the last page of this form

SKYLES DRILLING, INC.

WELL ID # L14850

(START CARD) # 138183

(1) OWNER:

Well Number: 01

Name **William & Adella Walter**Address **27200 Mtn. Top Rd.**City **Newberg, OR**State **OR** Zip **97132****(2) TYPE OF WORK:**New Well ☐ Deepening ☒ Alteration (repair/recondition) ☐ Abandonment ☐**(3) DRILL METHOD:**X Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger ☐
Other ☐**(4) PROPOSED USE:**X Domestic ☐ Community ☐ Industrial ☐ Irrigation ☐
Thermal ☐ Injection ☐ Livestock ☐ Other ☐**(5) BORE HOLE CONSTRUCTION:**Special Construction approval Yes ☒ No ☐ Depth of Completed Well **626** ft.
Explosives used Yes ☒ No ☐ Type ☐ Amount ☐

HOLE			SEAL			Amount	
Diameter	From	To	Material	From	To	sacks or pounds	
6	424	626	Seal Unchanged				

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E ☐
Other ☐Backfill placed from ☐ ft. to ☐ ft. Material ☐
Gravel placed from ☐ ft. to ☐ ft. Size of gravel ☐**(6) CASING/LINER:**

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	6	+1	118	.250	X		(X)	
	NoChange							
Liner:	4	6	626	160#		X	X	

Final location of shoe(s) **None****(7) PERFORATIONS/SCREENS:**

X Perforations		Method		Material			
From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
595	625	1/8x3	140				(X)

(8) WELL TESTS: Minimum testing time is 1 hourPump ☐ Bailer ☐ X Air ☐ Flowing Artesian ☐Yield gal/min **13** Drawdown **625** Drill stem at **1 hr.**Temperature of Water **55** Depth Artesian Flow found ☐Was a water analysis done? ☐ Yes ☐ By whom ☐Did any strata contain water not suitable for intended use? ☐ Too little ☐Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other ☐Depth of strata: ☐**(9) LOCATION OF WELL by legal description:**County **Yamhill** Latitude ☐ Longitude ☐
Township **3S** or S. Range **2W** E or W. of WM. ☐
Section **5** SW 1/4 NE 1/4
Tax lot **400** Lot ☐ Block ☐ Subdivision ☐
Street Address of Well (or nearest address) **27200 Mtn. Top Rd., Newberg, OR****(10) STATIC WATER LEVEL:**408 ft. below land surface. Date **4/4/01**
Artesian pressure ☐ lb. per square inch. Date ☐**(11) WATER BEARING ZONES:**Depth at which water was first found **426**

From	To	Estimated Flow Rate	SWL
Before	deepening	1	408
574	625	12	408

(12) WELL LOG:

		Ground elevation	
Material	From	To	SWL
Basalt, Gray & Brown, Broken	420	426	408
Basalt, Gray & Brown, Fractured (formation was caving, cemented off with 10 sacks)	426		
Basalt, Brown & Gray, Fractured	486	489	
Basalt, Gray & Brown, Fractured	489	495	
Basalt, Gray	495	514	
Basalt, Gray & Brown, Fractured	514	533	
Basalt, Multicolored, Fractured	533	546	
Basalt, Brown & Gray, Porous	546	552	
Basalt, Gray & Brown, Fractured	552	555	
Basalt, Gray Fractured	555	560	
Basalt, Multicolored, Fractured	560	567	
Basalt, Gray Fractured	567	574	
Basalt, Gray & Brown, Fractured	574	580	408
Basalt, Gray w/ Blue & Green, Fractured @ Times	580	625	408
Clay, Multicolored	625	626	

RECEIVEDSKYLES DRILLING, INC.
1165 Molalla Avenue
Oregon City, OR 97045
503-656-2663

APR 16 2001

WATER RESOURCES DEPT.
SALEM, OREGONDate started **4/2/01**Completed **4/4/01****(unbonded) Water Well Constructor Certification:**

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to my best knowledge and belief.

Signed *[Signature]*WWC Number **1715**Date **4-11-01****(bonded) Water Well Constructor Certification:**

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

Signed *[Signature]*WWC Number **1592**Date **4-11-01**

ORIGINAL & FIRST COPY - WATER RESOURCES DEPARTMENT

SECOND COPY - CONSTRUCTOR

THIRD COPY - CUSTOMER

RECEIVED

JAN 16 1998

Skyles Drilling, Inc.
1169 McJalla Ave.
Oregon City, OR 97045
656-2683

Yamh
50941

WATER RESOURCES DEPT.
STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)

WELL ID. # L 14850

START CARD # 110218

Instructions for completing this report are on the last page of this form.

(1) OWNER: Well Number 01
Name William & Adella Walter
Address 156 N.W. Cherry St.
City Dundee State Or. Zip 97115

(2) TYPE OF WORK
☒ New Well ☐ Deepening ☐ Alteration (repair/recondition) ☐ Abandonment

(3) DRILL METHOD:
☒ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger

☒ Other Holte

(4) PROPOSED USE:
☒ Domestic ☐ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☐ Livestock ☐ Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval ☐ Yes ☒ No Depth of Completed Well 416 ft.
Explosives used ☐ Yes ☒ No Type _____ Amount _____

HOLE		SEAL		Sacks or pounds	
Diameter	From To	Material	From To		
10	0 50	Bentonite	50 0	18	sacks
7 1/2	50 118				
6	118 416				

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E

☒ Other Poured Dry
Backfill placed from _____ ft. to _____ ft. Material _____
Gravel placed from _____ ft. to _____ ft. Size of gravel _____

(6) CASING/LINER:

Diameter	From To	Gauge	Steel	Plastic	Welded	Threaded
Casing: 6"	+3 118	25	0	☒	☒	☐
Liner: 4"	1 416	160	☐	☒	☒	☐

Final location of shoe(s) None Used

(7) PERFORATIONS/SCREENS:

From To	Slot size	Number	Diameter	Material	Casing	Liner
397 415	1/8x3	70			☐	☒

(8) WELL TESTS: Minimum testing time is 1 hour

☐ Pump Yield gal/min	☐ Baller Drawdown	☒ Air Drill stem at	☐ Flowing Artesian Time
30		414	1 hr.

Temperature of water 55° Depth Artesian Flow Found _____
Was a water analysis done? ☐ Yes By whom _____

Did any strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other _____
Depth of strata: _____

(9) LOCATION OF WELL by legal description:

County Yamhill Latitude _____ Longitude _____
Township 3 South or S Range 2 West E or W. WM.
Section 5 SW 1/4 NE 1/4
Tax Lot 400 Lot _____ Block _____ Subdivision _____
Street Address of Well (or nearest address) 27200 Mt. Top Rd.
Newberg, Or.

(10) STATIC WATER LEVEL:

350 ft. below land surface. Date 12-16-97
Artisan pressure _____ lb. per square inch. Date _____

(11) WATER BEARING ZONES:

Depth at which water was first found 386

From	To	Estimated Flow Rate	SWL
386	416	30	350

(12) WELL LOG:

Ground Elevation _____

Material	From	To	SWL
Basalt Brown & Gray weath	0	14	
" Gray & Brown Soft	14	26	
" Gray & Brown Broken w/	26		
Loose @ 45' to 84'		106	
" Gray	106	110	
" Gray & Brown Broken	110		
Loose @ Times (Cemented #8)		175	
Basalt Gray & Brown porous	175	181	
" Gray Fractured w/Seal 181			
of Brown Broken @ times Cemented		207	
" Extremely porous Cemented		207	
(No return)		277	
" Gray Cemented	277	300	
" Gray & Brown Fract.	300	378	
" Gray	378	386	
" gray & Brown Broken	386	424	350

Date started 11-25-97 Completed 12-16-97

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

Signed Shawn D. Brown WWC Number 1601 Date 1-6-98

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

Signed Steven C. Bland WWC Number 1592 Date 12-23-97