



C A M I N O D O N D I E G O N . E .

EXHIBIT A
IMPROVEMENT LOCATION REPORT



SCALE 1" = 20'
DRAWN BY: SDR
11/07/2023
23-0769.DWG

THIS IS NOT A BOUNDARY SURVEY AND MAY NOT BE SUFFICIENT FOR THE REMOVAL OF THE SURVEY EXCEPTION FROM AN OWNERS TITLE POLICY. IT MAY OR MAY NOT REVEAL ENCROACHMENTS, OVERLAPS, CONFLICTS IN BOUNDARY LINES, SHORTAGES IN AREA OR OTHER MATTERS WHICH WOULD BE DISCLOSED BY AN ACCURATE BOUNDARY SURVEY

HARRIS SURVEYING, INC.
1308 CIELO VISTA DEL SUR, NW
CORRALES, NEW MEXICO 87048
PHONE: (505) 250-2273
E-MAIL: harrissurveying51@gmail.com

LEGAL

LOT NUMBERED TWENTY (20) IN BLOCK NUMBERED THREE (3) OF VALLE ENCANTADA ADDITION CITY OF ALBUQUERQUE, NEW MEXICO, AS THE SAME IS SHOWN AND DESIGNATED ON THE PLAT THEREOF, FILED IN THE OFFICE OF THE COUNTY CLERK OF BERNALILLO COUNTY, NEW MEXICO, ON NOVEMBER 16, 1967.

THIS IS TO CERTIFY:

PLAT REFERENCE: Bearings, distances and/or curve data are taken from the following plat. (including filing information if the plat is a filed plat).

GENERAL NOTES:

I FURTHER CERTIFY as to the existence of the following at the time of said inspection:

Page 1 of 2