

List of Improvements
1008 Glen Chester Drive, Flower Mound, TX 75022

- Sprinklers
- Pool resurfacing
- Pool heater
- Pool salt system
- Interior paint throughout
- Landscaping
- Landscape lights
- Primary bathroom remodel
- Primary closets remodel
- Plantation shutters (3 rooms)
- Renovated wooden stairs and wrought iron railing
- Outside fire pit
- Kitchen refresh with backsplash/shaker cabinets/lights
- Fireplace new logs and refurbish pilot