



# St. Johns Court HOA 2021 Building Envelope Rehabilitation

<https://stjohnscourthoa.com/>






Pressure Intake Pipes Replaced




Pressure Intake Pipes Replaced



Pressure Intake Pipes Replaced



Pressure Intake Pipes Replaced



Hot Water Expansion Tanks Installed



Lead Toilet Drain Pipes- ABS Replaced



Lead Toilet Drain Pipes- ABS Replaced



New Backflow Check Valve Installed



New Mainline Pipe Installed



New Mainline Pipe Installed




New Landscaping Irrigation



Gutter Cleanouts



Roof Venting Flashed




New Bathroom Vents in Each Unit




Exterior Bathroom Vent Exitpoint



Optional Dryer Vents Installed




Missing Attic Vent Ducting  
Installed



Missing Attic Insulation  
Installed



New Doors Installed



New Windows Installed




Upper Walkway Cosmetic  
Cracks



Upper Walkway Seal



Building Footing Weather  
Seal



New LED Lights Installed

--end--