

Phone Number: 000-0000

Due for Service: 5/5/2025

First Name: Michelle

Next Service Time: 5/5/2027

Last Name: Redman

Tank Size: 2-1000 W/ Filter

Address: 98 Musquash Rd

City: Hudson

State: NH

Zip Code: 03051

Visual Check of System

| Condition of Tank | Conditions of Baffles in Tank | Condition of Leach Bed |
|---|--|---|
| <input checked="" type="checkbox"/> OK | <input checked="" type="checkbox"/> OK | <input type="checkbox"/> OK |
| <input type="checkbox"/> Good Bacteria Action | <input type="checkbox"/> Needs Replacing | <input type="checkbox"/> Run Back |
| <input type="checkbox"/> Over Due | | <input type="checkbox"/> Leaking from Side |
| | | <input type="checkbox"/> Working over Inverter Pipe from Side |

History and Comments

Cell ~~XXXXXXXXXX~~

04/05/06/08/14

11/17/16 Pump/Dig both tanks. Paid in full.

8/14/19 Pump Both Tanks/Clean Filter. All Ok. Paid in full.

05/12/21 Pump/Clean Filter /Dig. All Ok. Paid by CC #0343.

04/12/23 Pump/Clean Filter/Dig. All Ok. New owner. Paid by check, which was mislocated. Paid by CC #9907.

05/05/25 Pump both tanks \$520.00/Clean Filter \$35.00/Dig \$100.00. Will mark area in the front. Please give quote for risers. Does she need to pump both tanks each time? Has CC #9907 on file but will pay by check.

| Service Charge | Amount |
|-------------------------|------------|
| Pump <i>low</i> | <i>310</i> |
| Dig Cover | <i>50</i> |
| Snake / Repair Line | |
| Repair / Replace Baffle | |
| Other | |
| Total: | <i>360</i> |