



96 North Rd East Kingston NH 03827
603-772-3494 info@bodwells.com

INVOICE NO. 1620

CUSTOMER Patrick Harrington		DATE 5/12/26
ADDRESS 109 Langford Rd		
TOWN Raymond NH		
PHONE 201-488-3943	TECHNICIAN bb	
CASH	CHECK	VENMO
		CHARGE <input checked="" type="checkbox"/>
		ON ACCOUNT

Quantity	Description	Rate	Amount
1500	Tank pumping		450.00
	Dig Find & Dig		
1	Clean filter (CF) (CCF)		25.00
	Pumping Fees (X-SL) (X-H) (WPS)		
	Emergency (ND) (SD) (COM) (WKN) (HOL)		
Total			\$475.00

Complementary Visual Inspection (If applicable)

Inlet Baffle Type: (PVC) (Plastic) (Concrete)	Condition: (Good) (Deteriorated) (Missing)
Outlet Baffle Type: (PVC) (Plastic) (Concrete)	Condition: (Good) (Deteriorated) (Missing)
Effluent back flow from outlet? (Yes) (No) (NA)	Did you notice any cracks? (Yes) (No) (NA)

Notes:

We are not responsible for grass, driveways, walkways, irrigation, underground utilities, and broken or damaged covers.

ALN	DUR	EXE	HAM
NG	NM	POR	OTHE

THANK YOU!