



Rosco Electric Development Group, Inc.  
7015 Olive Boulevard  
Saint Louis MO 63130

June 2, 2026

Turnbull Family  
2772 Country Club Drive, City of Pasadena Hills, MO 63121

To whom it may concern,

A limited inspection for knob and tube wiring was performed at the above job address.

Knob and tube was not observed in the following locations:

Main electrical panel

Basement ceiling

3 living room receptacles replaced (2 exterior, 1 interior)

2 second floor switches opened

2 knobs observed in the Attic with one modern low voltage control wire on them. Likely abandoned HVAC install or control wiring. No 120V wiring observed on knobs and tubes.

By my observation the home did not originally include knob and tube wiring.

Wiring methods are those that followed the period.

Boxes, BX cable or NM cable, observed at all locations.

Sincerely,

Neal Rossel

Owner,, President, License holder, Electrician, Assistant to President, Assistant to the Assistant to President

314-608-1115

neal@roscoelectric.com