

SANDIA LAND SURVEYING LLC
15 CASA TERRENOS
PLACITAS, N.M. 87043
(505)867-1241


JOB NO.:
433-14

DATE:
12-16-2014

SCALE:
1"=50'

BOUNDARY SURVEY
LOT 116A
DIAMOND TAIL SUBDIVISION PHASE 2
SANDOVAL COUNTY
SANDOVAL COUNTY, NEW MEXICO

- NOTE: 1) BEARING BASE FOR THIS SURVEY
IS LEGAL DESCRIPTION OF RECORD.
 2) UNLESS OTHERWISE NOTED CORNERS ARE
FOUND REBAR W/CAP "TYREE SURVEYS 3516".
 3) FT000170939



LEGAL DESCRIPTION

LOT NUMBERED 116A (6) ON PLAT ENTITLED "CLAIM OF ADJUSTMENT LOTS 64A, 65A, 68A, 81A, 89A, 94A, 96A, 97A, 105A, 109A-110A, 115A-128A, & 133A, DIAMOND TAIL SUBDIVISION PHASE II, DIAMOND TAIL SUBDIVISION PHASE II, FILED IN THE OFFICE OF THE COUNTY CLERK OF SANDOVAL COUNTY, NEW MEXICO ON SEPTEMBER 21, 2009 IN VOL. 3, FOLIO 3107.

FLOOD CERTIFICATE:

IT IS HEREBY CERTIFIED THAT THE ABOVE DESCRIBED PROPERTY IS NOT LOCATED WITHIN A 100 YEAR FLOOD HAZARD BOUNDARY IN ACCORDANCE WITH HUD FEDERAL ADMINISTRATION FLOOD HAZARD BOUNDARY MAP DATED MARCH 18, 2008. ZONE "X", COMMUNITY PANEL NO. 350055 1950 D.

I, ANDREW S. MEDINA, NEW MEXICO REGISTERED PROFESSIONAL SURVEYOR NUMBER 12649, DO HEREBY CERTIFY THAT THE SURVEY AND PLAT SHOWN HEREON WERE PERFORMED, AND EXECUTED UNDER MY SUPERVISION AND MEETS THE "MINIMUM STANDARDS FOR LAND SURVEYS IN NEW MEXICO" AND IS TRUE AND CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF.

IN, WITNESS WHEREOF, this certificate is executed at Albuquerque, New Mexico on this 16TH
day of DECEMBER 20 14.

Andrew S. Medina
 Surveyor, Andrew S. Medina
 SANDIA LAND SURVEYING

N.M.P.S. No. 12649