

IMPROVEMENT LOCATION REPORT

THIS IS TO CERTIFY:

TITLE COMPANY TITLE ALLIANCE OF NEW MEXICO UNDERWRITER _____
LENDER N/A that on OCTOBER 05, 2026
I made an inspection of the premises situated at 63A CAMINO DE LAS HUERTA
PLACITAS SANDOVAL County, New Mexico

PLAT REFERENCE: Bearings, distances and/or curve data are taken from the following plat. (including filing information if the plat is a filed plat).

PLAT NAME LANDS OF HARRINGTON Filing Date, APRIL 18, 1986 Vo. 3 Folio 573-B

Page: _____

GENERAL NOTES:

The error of closure for this property is one (1) foot of error for every N/A feet along the perimeter of the legal description provided.

Easements shown hereon are listed in the Title Commitment No. _____ provided by the Title Insurance Company shown above.

See Exhibit "A" to the Improvement Location Report for a complete Legal Description and Sketch of the property in question. (Page 2 of 2)

Improvement location is based on previous property surveys. No monuments were set with this inspection report. This Tract is subject to all Easements, Restrictions and Reservations of record which pertain to the property in question.

This report is not to be relied upon for the establishment of fences, buildings and/or other future improvements.

I FURTHER CERTIFY as to the existence of the following at the time of said inspection:

1: Evidence of rights-of-ways, old highways or abandoned roads, lanes, trails or driveways sewer drains, water, gas or oil pipelines on or crossing the property in question.

NONE

2: Springs, streams, rivers, ponds or lakes located on or bordering on or through the property in question.

NONE

3: Evidence of cemeteries or family burial grounds located on the property in question.

NONE

4: Overhead Utility poles, anchors, pedestals, wires or lines overhanging or crossing the property in questions and serving other properties.

SEE SKETCH IF ANY

5: Joint driveways or walkways, joint garages, party walls or rights of support, steps or roofs used in common:

SEE SKETCH IF ANY

6: Apparent encroachments. If buildings, projections or cornices thereof, or signs affixed thereto, fences, walls or other indications of occupancy appear to encroach upon or overhang adjoining property or the like appear to encroach upon or overhanging the property in question.

SEE SKETCH IF ANY

7: Specific physical evidence of boundary lines on all sides of the property in question.

SEE SKETCH (PAGE 2 OF 2)

8: Is the property in question improved?

YES

9: Indications of recent building construction, alterations or repairs:

NONE

10: Approximate distances of structure or structures from at least two (2) property lines.

SEE SKETCH (PAGE 2 OF 2)

Anthony L. Harris (Surveyor) N.M.P.M. # 11463

The above information is based on boundary information taken from a previous survey and may not reflect that which may be disclosed by a boundary Survey.


Anthony L. Harris



EXHIBIT A

IMPROVEMENT LOCATION REPORT

LOT "B-1" AND LOT "B-2" OF LANDS OF HARRINGTON, AS THE SAME ARE SHOWN AND DESIGNATED ON THE PLAT ENTITLED "REPLAT OF LOTS A AND B, LANDS OF HARRINGTON, IN SECTION 32, T. 13 N., R. 5 E., N.M.P.M., SAN ANTONIO DE LAS HUERTAS GRANT, SANDOVAL, SANDOVAL COUNTY, NEW MEXICO," FILED IN THE OFFICE OF THE COUNTY CLERK OF SANDOVAL COUNTY, NEW MEXICO, ON APRIL 18, 1986, IN VOLUME 3, FOLIO 573-B.



THIS IS NOT A BOUNDARY SURVEY AND MAY NOT BE SUFFICIENT FOR THE REMOVAL OF THE SURVEY EXCEPTION FROM AN OWNERS TITLE POLICY. IT MAY OR MAY NOT REVEAL ENCROACHMENTS, OVERLAPS, CONFLICTS IN BOUNDARY LINES, SHORTAGES IN AREA OR OTHER MATTERS WHICH WOULD BE DISCLOSED BY AN ACCURATE BOUNDARY SURVEY



HARRIS SURVEYING, INC.
1308 CIELO VISTA DEL SUR, NW
CORRALES, NEW MEXICO 87048

PHONE: (505) 889-8056
E-MAIL: harrissurveying51@gmail.com