File Original and First Copy with Department of Ecology
Second Copy—Owner's Copy
Third Copy—Driller's Copy

WATER WELL REPORT

STATE OF WASHINGTON

Start Card No. 025727

Water Right Permit No. _____

(1) OWNER: Name Walt Houser Address 4115 NE. 259th St. Ridgefield,Wa.

(2) LOCATION OF WELL: County Clark NW ¼ NE ¼ Sec 25 T 4 N., R 1E W.M.

(2a) STREET ADDDRESS OF WELL (or nearest address) Same

(3) PROPOSED USE: XX Domestic ☐ Industrial ☐ Municipal ☐ ☐ Irrigation ☐ Test Well ☐ Other ☐ ☐ DeWater

(4) TYPE OF WORK: Owner's number of well (if more than one) _____
Abandoned ☐ New well XX Method: Dug ☐ Bored ☐ Deepened ☐ Cable ☐ Driven ☐ Reconditioned ☐ Rotary XX Jetted ☐

(5) DIMENSIONS: Diameter of well 6 inches. Drilled 138 feet. Depth of completed well 138 ft.

(6) CONSTRUCTION DETAILS:
Casing installed: 6 " Diam. from + 3'6" ft. to 129'6" ft.
Welded XX PVC 4" Diam. from 108 ft. to 138 ft.
Liner installed XX
Threaded ☐ _____ " Diam. from _____ ft. to _____ ft.

Perforations: Yes XX No ☐
Type of perforator used Saw
SIZE of perforations 6 in. by 1/16 in.
48 perforations from 118 ft. to 138 ft.
_____ perforations from _____ ft. to _____ ft.
_____ perforations from _____ ft. to _____ ft.

Screens: Yes ☐ No XX
Manufacturer's Name _____
Type _____ Model No. _____
Diam. _____ Slot size _____ from _____ ft. to _____ ft.
Diam. _____ Slot size _____ from _____ ft. to _____ ft.

AND Gravel packed: Yes XX No ☐ Size of gravel # 6 monterey
Gravel placed from 125 ft. to 138 ft.

Surface seal: Yes XX No ☐ To what depth? 18 ft.
Material used in seal Bentonite & hole plug
Did any strata contain unusable water? Yes ☐ No XX
Type of water? _____ Depth of strata _____
Method of sealing strata off _____

(7) PUMP: Manufacturer's Name _____
Type: _____ H.P. _____

(8) WATER LEVELS: Land-surface elevation above mean sea level _____ ft.
Static level 80 ft. below top of well Date 10-9-89
Artesian pressure _____ lbs. per square inch Date _____
Artesian water is controlled by _____ (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? Yes ☐ No XX If yes, by whom? _____
Yield: _____ gal./min. with _____ ft. drawdown after _____ hrs.
" " " "
" " " "

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level

Date of test _____
Bailer test 10 gal./min. with 32 ft. drawdown after 1 hrs.
Airtest _____ gal./min. with stem set at _____ ft. for _____ hrs.
Artesian flow _____ g.p.m. Date _____
Temperature of water _____ Was a chemical analysis made? Yes ☐ No XX

(10) WELL LOG or ABANDONMENT PROCEDURE DESCRIPTION

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of information.

MATERIAL	FROM	TO
Top soil	0	2
Clay	2	10
Sandy brown clay	10	18
Grey clay	18	26
Gravel, sand, clay	26	40
Gravel, sand	40	51
Cemented gravel	51	90
Cemented sand (water)	90	135
Grey clay	135	138

Work started 10-6-89 19. Completed 10-9-89 19

WELL CONSTRUCTOR CERTIFICATION:

I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and the information reported above are true to my best knowledge and belief.

NAME Hansen Drilling Co. Inc. (PERSON, FIRM, OR CORPORATION) (TYPE OR PRINT)

Address 6711 NE. 58th Ave. Vancuver,Wa. 98661

(Signed) Timothy D. Jones (WELL DRILLER) License No. 1342

Contractor's Registration No. HANSED*377NT Date Oct. 10,1989 19

(USE ADDITIONAL SHEETS IF NECESSARY)

ECY 050-1-20 (10/87) -1329- 3

The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.